

VEHICLE INSPECTION REPORT

Report #: NEJ7512

VEHICLE INFORMATION

Make: TOYOTA
Model: HILUX
Year: 2025
VIN: MR0BA3CD406626998
Color: RED
Mileage: 510 KM

Version: GR
Transmission: AUTOMATIC
Owner Name: NAGOYA EXPORTER JAPAN
Contact: +81 80-1451-8459
Date of Inspection: 03/JULY/2026

INSPECTION CHECKLIST

Component	Pass	Fail	N/A	Remarks
Exterior Body Condition	☒	☐	☐	
Paint & Finish	☒	☐	☐	
Windshield & Glass	☒	☐	☐	
Headlights & Tail Lights	☒	☐	☐	
Tires & Wheels	☒	☐	☐	
Brakes (Front & Rear)	☒	☐	☐	
Engine Performance	☒	☐	☐	
Transmission	☒	☐	☐	
Suspension & Steering	☒	☐	☐	
Exhaust System	☒	☐	☐	
Battery & Electrical	☒	☐	☐	
AC / Heating System	☒	☐	☐	
Interior Condition	☒	☐	☐	
Seat Belts & Airbags	☒	☐	☐	
Dashboard & Gauges	☒	☐	☐	
Horn & Wipers	☒	☐	☐	
Fluid Levels	☒	☐	☐	
Undercarriage	☒	☐	☐	

ADDITIONAL COMMENTS / RECOMMENDATIONS

VEHICLE INSPECTED AND FOUND TO BE IN GOOD OVERALL CONDITION. ENGINE, TRANSMISSION, SUSPENSION, BRAKING SYSTEM, ELECTRICAL COMPONENTS, AND SAFETY FEATURES WERE CHECKED AND FOUND TO BE FUNCTIONING PROPERLY. NO MAJOR MECHANICAL DEFECTS, STRUCTURAL DAMAGE, OR FLUID LEAKS WERE OBSERVED AT THE TIME OF INSPECTION. VEHICLE IS RECOMMENDED FOR EXPORT AND REGULAR OPERATION. ROUTINE MAINTENANCE SHOULD BE CARRIED OUT ACCORDING TO THE MANUFACTURER'S SERVICE SCHEDULE.

Inspector Name: SHOHEI KATO **Signature:** Shohei Kato **Date:** 03/JULY/2026